

FIG. 1




FIG.2


























NAMES OF SPOTS	PROCESS			
	1 (2002.5.30)	2 (2002.6.15)	3 (2002.6.30)	4 (2002.7.15)
CONCRETE 1				
CONCRETE 2				
FRONTAL APPEARANCE				
REAR APPEARANCE				
GAS PIPE				
WATER PIPE				
1ST FLOOR INTERIOR				
2ND FLOOR INTERIOR				

FIG.3



<IMAGE MANAGEMENT APPARATUS>

<DIGITAL CAMERA>



<IMAGE MANAGEMENT APPARATUS>

<DIGITAL CAMERA>





FIG.4B

FIG.5



PROCESS

1 (2002.5.30) 2 (2002.6.15) 3 (2002.6.30) 4 (2002.7.15)

NAMES OF SPOTS
























CONCRETE 1				
CONCRETE 2				
FRONTAL APPEARANCE				
REAR APPEARANCE				
GAS PIPE				
WATER PIPE				
1ST FLOOR INTERIOR				
2ND FLOOR INTERIOR				

FIG.6

FIG. 7

